

This drawing, specifications, and concepts contained here in are the sole property of Dart Aerospace, and may not be reproduced or used in any fashion without the prior written permission of Dart Aerospace Eugene, OR.


revisions								
REV	ECR	DESCRIPTION	DATE	INITIAL	APPROVED			
1		ADDED TOLERANCES	7/22/2013	JAG				
1A	14-0095	CH'D TITLE BLOCK WAS RED BARN IS DART. ADDED NOTE 2.	7/28/2014	DPD	RW			











SEE ATTACHED DEVIATION

- NOTES: 1. NICKEL PLATE .0004 .0006, BAKE AFTER PLATING.
- 2. BAG & LABEL WITH BATCH NUMBER.

DART							
TITLE	LIF	TER B	USHIN	G			
DWG NO.		4.51	VR-7		1A		
MAT'L 4140			DRAWN BY:				
	OTHERWISE		APPROVED	D Wee	e		
.XXX ± .005		IONS ± 1/32	HEAT TREAT	HRC 40-44			
.XX ± .01		FINISH	SEE NOTE 1				
1. BREAK ALL	SHARP EDG	ES .015 x 45°	SPEC				
OR .015R 2. DIMENSION	AL LIMITO AD	DI V ACTED	USED ON MODEL				
PLATING	AL LIMITS AP	PLIAFIER					
SCALE	2:1	DATE		SHEET 1 O	F 1		

ASSY QTY	ASSY QTY	В/О	Part #	UNIT QTY	Description	Material	B/O INFORMATION OR SPECIFICATIONS
			4.5NR-7	1	LIFTER BUSHING	4140	Ø1/2 X 3/4

Entered: Date:	ered:Date: WORK ORDER NON-CONFORMANCE / ROUTE UPDATE AEROSPACE						
NCR No.	D. A. Alderson, C.						
lah.	DISPOSITION	DEPARTMENT/PROCESS					
Job:	Rework	Skid-tube Cross tube	Eng. (Non-AW)	Engineering			
Part No. 4.5 NR - 7	Scrap	Machining Small Fab		Water Jet			
REV 1A	Use-as-is	Large Fab Finishing	Rec/Store/Packaging	Supplier Quality			
Date: 2010 GC 111	Sequence #:	QTY Affected :		MRB (QSI042)			
Date: 2019-05-14				184			
Description Wor	k Order Deviation	Dispositio	n	VV			
				Completed By			
MATERIAL 4140, NIC	CKEL PLATED, 40-44 RC	- THIS DEVIATION IS A					
CAN BE REPLACE B'		TO USE AS 1S.		Lead hand / Supervisor			
· ·	· ·						
14-4 H900, NO FIN	VISH, NO HEAT TREAT	- FIT, FORM AND FUNCTION WILL					
NEEDED	•	BE AS ORIGINALLY INTENDED					
_		QC / QA Coordinato					
*		QC / QA Cobrama					
	~						
Root Cause		FAULT CATEGORY					
	Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong			
Operator	Bending	Misaligned/off center	Folio/Program	Outside Tolerance			
Manufacturing Process	Crushing	BOM/Route	Grain Direction	Drawing			
Equip/Tooling	Cracks	Broken/Damage/Defect	Weld	Finish Part Lost/Missing			
Handling/Presservation	Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled Out of Sequence	Misread			
Material	Marks/Chatter	Drill Holes	Off-set/Set-up	IVIISI COU			
Product Improvement Mislabeled		Fit/Function	Oll-Set/Set-up				
Process Improvement	Other/Details:						
Human Factors							
	}						